

LABOR AND MATERIALS

| | | | | |
|----|--------------------------|---|---------------------|----|
| 1 | Copper Lead | Connection | $\frac{3}{4}$ " | \$ |
| 1 | Curb | Cock Valve F. Serv. | $\frac{3}{4}$ " in. | \$ |
| 1 | Service box Old returned | Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ | | \$ |
| 25 | Ft. | Copper Gal. Gal. Pipe at | $\frac{3}{4}$ " in. | \$ |
| | Nipples | in. at | | \$ |
| 1 | Bushings | $\frac{3}{4}$ " to $\frac{1}{2}$ " in. at | | \$ |
| | Red'g Inc'g | Coupl'gs to in. at | | \$ |
| | Union | in. at | | \$ |
| | Meter | in. at | | \$ |
| | Compound Joints | at | | \$ |
| | Maintenance Foreman | | | \$ |
| | Hrs. Water Maint. Man-1 | at | | \$ |
| | Hrs. Water Maint. Man-2 | at | | \$ |
| | Hrs. Garage Foreman | at | | \$ |
| | Hrs. Labor | at | | \$ |
| | Hrs. Compressor | at | | \$ |
| | Trucking | | | \$ |
| | Pav't Patch | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |

DAVIS

St. No. 20

Name of Owner

Labor and Mat'l. Report

OCT. 4 19 35

DAVIS ST.



25'8" 22'3"

● Curb Box

GRANT AVE

4" Main

Elev. of Main at tap 4 1/2'

Gate at ●

● Gate at

TAP ON GRANT

● Curb Box

OLD TAP SHUT OFF AT MAIN