

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$ "	\$
	Lead		
1	Curb	} Cock Valve T.S. & V. } $\frac{3}{4}$ " in.	\$
1	Service box Old returned	} Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ }	\$
25	Ft. $\frac{3}{4}$ "	} Copper Gal. Gal. }	Pipe at \$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g Inc'g } Coupl'gs	to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$

St. DAVIS
Ave. No. 32
Name of Owner _____

Labor and Mat'l. Report OCT. 15 1936



38' 10" 26' 5"

● Curb Box

$\frac{6}{4}$ " Main Elev. of Main at tap 5'
Gate at ● ● Gate at

● Curb Box

OLD TAP SHUT OFF