

## LABOR AND MATERIALS

1	Copper Lead	Connection	3/4"	\$	2.29
1	Curb	{ Cock Valve T.S. & V. }	3/4" in.	\$	2.70
1	Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }		\$	4.25
7	Ft.	3/4 in. { Copper G.I. C.I. }	Pipe at	35 \$	2.45
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	{ Coupl'gs to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	12.51
	Compound Joints	at		\$	
	Hrs. Water Maint. Man—1	at		\$	
7	Hrs. Water Maint. Man—2	at	1.02	\$	7.14
7	Hrs. Labor—	at	.91	\$	6.37
	Hrs. Labor—	at		\$	
2	Hrs. Compressor	at	1.20	\$	2.40
	Compensation Ins. at \$	per C.		\$	30
	Trucking			\$	6.78
	Pav't Patch			\$	
	O'head			\$	
				\$	37.68

Davis  
 (Rear 21 G. Ave.)

Name of Owner

Barber

St.  
 Pt.  
 Ave. No. 9

---

Labor and Mat'l. Report July 25 19 50

RAZED - 1994

● Curb Box

---

4" Main

Gate at ●

Elev. of Main at tap 6'

● Gate at

● Curb Box

LSM-5C 10-21-49