

LABOR AND MATERIALS

1	Copper Lead	} Connection	$\frac{3}{4}$	in.	\$	
1	Curb					} Cock Valve T. S. & V.
1	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ }			\$	
30	Ft. $\frac{3}{4}$					} Copper Pipe
	Nipples	in.	at	\$		
	Bushings	to	in.	at	\$	
	Red'g Inc'g	} Coupl'gs	to	in.	at	\$
	Union					
	Meter	in.	at	\$		
	Compound Joints	at	\$			
	Maintenance Foreman	\$				
	Hrs. Water Maint. Man—1	at	\$			
	Hrs. Water Maint. Man—2	at	\$			
	Hrs. Garage Foreman	at	\$			
	Hrs. Labor—	at	\$			
	Hrs. Compressor	at	\$			
	Trucking	\$				
	Pav't Patch	\$				
		\$				
		\$				
		\$				
		\$				
		\$				

DIX Ave. No. 16

Name of Owner  
TAX ID # 303.13-8-46

Labor and Mat'l. Report SEPT. 28 1928



50'2"      4'6"

● Curb Box

4" Main Elev. of Main at tap 4'

Gate at ● ● Gate at

● Curb Box