

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$		\$ 1.79
1	Curb	Clock Valve T.S. & V.	$\frac{3}{4}$	in.	\$ 2.61
1	Service box Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff for Rdway			\$ 1.82
10	Ft.	$\frac{3}{4}$ in.	Copper Galv. Iron Cast Iron	Pipe at 23	\$ 3.45
	Nipples	in.	at		\$
	Bushings	to	in.	at	\$
	Red'g Inc'g	Couplings	to	in.	at \$
	Union	in.	at		\$
	Meter	in.	at		\$
	Lead Joints	at			\$
	Compound Joints	at			\$
	Hrs. Foreman	at			\$
2	Hrs. Chauffeur	at	$8\frac{1}{2}$		\$ 1.65
	Hrs. Tapper	at			\$
1	Hrs. Labor	at	$7\frac{1}{2}$		\$ 72
	Hrs. Labor	at			\$
	Hrs. Compressor	at			\$
	Compensation Ins.				\$ 1.07
	Trucking				\$ 5.00
	Builders Use of Water				\$
	<i>Tajak Warsinski</i>				\$
					\$
					\$
					\$
					\$
					\$
					\$ 18.11

99-46
 St. Pl. Ave. No. 73

Name of Owner
Milton WHESTEMAN'S BODY SHOP

Labor and Mat'l. Report Nov 19 1946

Elev. of Main at tap 5'

Gate at ● Gate at ●

● Curb Box

Tap on Dix Ave.

LBM-5C-6-1-45