

LABOR AND MATERIALS

1 Copper } Connection 1 1/2" \$ _____
 Lead }
 1 Curb } Cock } 2 in. \$ _____
 } Valve }
 } T.S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 }
 } Buff. or Rdway } small \$ _____
 7 Ft. 2 in. { Copper } Pipe at \$ _____
 } G.I. }
 } C.I. }
 Nipples in. at \$ _____
 1 Bushings 2" to Male Adapter in. at \$ _____
 Red'g } BRASS
 1 Inc'g } Coupl'gs. 2 to 2 in. at \$ _____
 Union in. at \$ _____
 Meter in. at \$ _____
 Lead Joints at \$ _____
 Compound Joints at \$ _____
 Maintenance Foreman \$ _____
 Hrs. Water Maint. Man-1 at \$ _____
 Hrs. Water Maint. Man-2 at \$ _____
 Hrs. Garage Foreman at \$ _____
 Hrs. Labor at \$ _____
 Hrs. Compressor at \$ _____
 Compensation Ins. at \$ _____ per C. \$ _____
 Trucking \$ _____
 Pav't Patch \$ _____
Tap by Giesard, Miller \$ _____
& Co. 12-31-57 \$ _____
 O'head \$ _____
 \$ _____

V

St. Dix Ave. No. 79-81

Name of Owner NEW CAR SALES
Whiteman Chev.

Labor and Mat'l. Report Dec. 31 1957

DIX AVE.

Show Room

Door

Garage Door

70' 7"

60' 10"

Curb Box

Leonard St.

6" Main Elev. of Main at tap 3'

Gate at • Gate at

• Curb Box

Tap on Leonard St.

LSM-5C-2-5 56