

LABOR AND MATERIALS

1	Copper	} Connection	$\frac{3}{4}$	\$	
	Lead				
1	Curb	} T.S. & V.	$\frac{3}{4}$ in.	\$	
	Cock Valve				
1	Service box	} {	Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$	
	Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$		
6	Ft. $\frac{3}{4}$ in.	} Pipe at	Copper	\$	
			G.I.		
			G.I.		
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	} Coupl'gs	to in. at	\$	
	Inc'g				
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man	—1 at		\$	
	Hrs. Water Maint. Man	—2 at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	

DIX

SE
PL
Ave. No. 91

Name of Owner

Labor and Mat'l. Report

APR 5 1932



36-10 36-5

● Curb Box

6" Main PROSPECT ST Elev. of Main at tap 3'

Gate at ●

● Gate at

● Curb Box

TAP ON PROSPECT
NEW HOUSE