

LABOR AND MATERIALS

6" style #80 Dresser  
 1 Copper Lead Connection *Repair Sinks* \$  
 1 Curb Cock Valve } 2 in. \$  
 T.C. & V.  
 1 Service box { Short 3 1/2 x 4 1/2 }  
 Old returned { Long 4 1/2 x 5 1/2 }  
 Buff or Rdway } \$  
 34 Ft. 2 in. { Copper } Pipe at \$  
 { G.I. }  
 { G.I. }  
 2 Nipples Brass in. at 1- 2 x 2 1/2" \$  
 1- 2 x 4" \$  
 Bushings to in. at \$  
 Red'g }  
 1 Inc'g } Coupl'gs 2 to 2 in. at \$  
 Cop to Cop  
 1 Union Elbow in. at Brass 2" \$  
 Meter in. at Wheel \$  
 1 Lead Joints at 2" Gate Valve \$ at main  
 1 Compound Joints at Male \$  
 Maintenance Foreman Adapter \$  
 Hrs. Water Maint. Man-1 at \$  
 Hrs. Water Maint. Man-2 at \$  
 Hrs. Garage Foreman at \$  
 Hrs. Labor at \$  
 Hrs. Compressor at \$  
 Compensation Ins. at \$ per C \$  
 Trucking \$  
 Pav't Patch \$  
 Tap by Miller & Co \$  
 6-4-58 \$  
 O'head May + June \$  
 \$

St.   
 Pl.   
 Ave. No. 152

Name of Owner  
 Dix  
 Glens Falls Bottling Co.  
 Pepsi-Cola  
 Labor and Mat'l. Report June 6 1958

