

LABOR AND MATERIALS

Copper	} Connection		\$
Lead			
2 Curb	{ Clock Valve T.S. & V. }	3/4 in. 2.61	\$ 5.22
1 Service box Old returned			
6 Ft. 3/4 in.	{ Copper Galv. Iron Cast Iron }	Brass Pipe at	\$
1 Nipples 1/4 in. at 6"			\$
Bushings	to	in. at	\$
Red'g Inc'g	} Couplings	to	in. at
1 Union 1/4 in. at			
Meter		in. at	\$
1 Lead Joints at 1/4 X 3/4 Galv. Iron			\$
Compound Joints at			\$
1 Hrs. Foreman at 9 Brass			\$
1 Hrs. Chauffeur at 4 2" long			\$
1 Hrs. Tapper at W.W.M. 9.21			\$ 1.85
8 Hrs. Labor at 7.112			\$ 5.72
Hrs. Labor at			\$
Hrs. Compressor at			\$
Compensation Ins.			\$ 21
Trucking			\$ 1-
Builders Use of Water			\$
Tap by Meter			\$
			\$
			\$
			\$
			\$

158-746

Dix Ave Ave. No. 217

Name of Owner W. W. S. C.
Glen Falls Publishing Co
Broadcasting Co

Labor and Mat'l. Report Nov 20 1946

52'5" 41'6"

● Curb Box

8" Main Elev. of Main at tap 4 1/2

Gate at ● Gate at ●

● Curb Box

LSM-5C-6-1-45