

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$	\$	
1	Lead		\$	
1	Curb	} Cock Valve } $\frac{3}{4}$ in.	\$	
			} T. S. & V. }	\$
				\$
	Service box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$	
	Old returned		} Long $4\frac{1}{2} \times 5\frac{1}{2}$	\$
24	Ft. $\frac{3}{4}$ in.	} Copper	\$	
			} C.I. } Pipe at	\$
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g	} Coupl'gs	\$	
	Inc'g		to in. at	\$
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	

DUDLEY St. PE. Ave. No. 7

Name of Owner
TAX ID # 309.15-10-10

Labor and Mat'l. Report JULY 13 1928



21-5 29-6

● Curb Box

4" Main Elev. of Main at tap 5'

Gate at ● Gate at

● Curb Box

NEW HOUSE