

LABOR AND MATERIALS

1 ~~Curb~~ } Connection 2" \$
 1 Curb { Clock Valve } 2" in. \$
 { T-S & V. }
 1 Service box { Short 3 1/2 X 4 1/2 } \$
 Old returned { Long 4 1/2 X 5 1/2 }
 { Buff or Rdway }
 11 Ft. 2 in. { Copper } Pipe at \$
 { Galv. Iron }
 { Cast Iron }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g } Couplings to in. at \$
 Inc'g }
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 3 Hrs. Foreman at W.W.M. 925 \$
 Hrs. Chauffeur at \$
 Hrs. Tapper at \$
 7 Hrs. Labor at @.715 \$
 Hrs. Labor at \$
 Hrs. Compressor at \$
 Compensation Ins. \$
 Trucking \$
 Builders Use of Water \$
 Trip by Miller \$
 \$
 \$
 \$

11-13 ✓

St. Dudley
Pl. Ave. No. 9

Name of Owner
Ray Pezall

Labor and Mat'l. Report Nov 18 1946

26'7" 47'5"
● Curb Box

Bush St.

6 Main Elev. of Main at tap 5

Gate at ● ● Gate at

● Curb Box

This tap on Bush St

LSM-5C-6-1-45

