

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$	\$
1	Curb		} Cock Valve } $\frac{3}{4}$ in. \$
		T. S. & V.	
1	Service box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$	\$
12	Ft. $\frac{3}{4}$ in.		} Copper C.I. C.I.
	Nipples	in. at \$	
	Bushings	to in. at \$	
	Red'g Inc'g	} Coupl'gs to in. at \$	
	Union		in. at \$
	Meter	in. at \$	
	Compound Joints	at \$	
	Maintenance Foreman	\$	
	Hrs. Water Maint. Man-1	at \$	
	Hrs. Water Maint. Man-2	at \$	
	Hrs. Garage Foreman	at \$	
	Hrs. Labor	at \$	
	Hrs. Compressor	at \$	
	Trucking	\$	
	Pav't Patch	\$	
		\$	
		\$	
		\$	
		\$	

St. ELIZABETH
Ave. No. 12

Name of Owner _____

Labor and Mat'l. Report AUG. 6 1934



21-10" 7'

● Curb Box

6" Main Elev. of Main at tap 5'
Gate at ● Gate at

● Curb Box

OLD SHOT OFF AT MAIN