

LABOR AND MATERIALS

| | | | | |
|----|-------------------------|---|--|----|
| 1 | Copper | } Connection $\frac{3}{4}$ | \$ | |
| | Lead | | | |
| 1 | Curb | } Cock Valve T. S. & V. } $\frac{3}{4}$ in. | \$ | |
| | Service box | | } Short $3\frac{1}{2}$ x $4\frac{1}{2}$ } Long $4\frac{1}{2}$ x $5\frac{1}{2}$ } | \$ |
| | Old returned | | | |
| 28 | Ft. | } Copper } Pipe at | \$ | |
| | $\frac{3}{4}$ in. | | } C.I. } | |
| | Nipples | in. at | | \$ |
| | Bushings | to in. at | \$ | |
| | Red'g | } Coupl'gs. to in. at | \$ | |
| | Inc'g | | | |
| | Union | in. at | \$ | |
| | Meter | in. at | \$ | |
| | Compound Joints | at | \$ | |
| | Maintenance Foreman | | \$ | |
| | Hrs. Water Maint. Man-1 | at | \$ | |
| | Hrs. Water Maint. Man-2 | at | \$ | |
| | Hrs. Garage Foreman | at | \$ | |
| | Hrs. Labor | at | \$ | |
| | Hrs. Compressor | at | \$ | |
| | Trucking | | \$ | |
| | Pav't Patch | | \$ | |
| | | | \$ | |
| | | | \$ | |
| | | | \$ | |
| | | | \$ | |
| | | | \$ | |

St. ELIZABETH
 Ave. No. 13
 Name of Owner
 TAX ID # 302.20-19-18

Labor and Mat'l. Report Aug. 27 1926



● Curb Box

6" Main Elev. of Main at tap 4 1/2'
 Gate at ● Gate at

● Curb Box

NEW HOUSE