

LABOR AND MATERIALS

1	Copper } Connection $\frac{3}{4}$	\$
	Lead }	
1	Curb } Cock Valve } $\frac{3}{4}$ in.	\$
	T.S. & V. }	
1	Service box } Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$
	Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$	
26	Ft. $\frac{3}{4}$ in. } Copper } Pipe at	\$
	Nipples in. at	\$
	Bushings to in. at	\$
	Red'g } Coupl'gs to in. at	\$
	Inc'g }	
	Union in. at	\$
	Meter in. at	\$
		\$
	Compound Joints at	\$
	Maintenance Foreman	\$
	Hrs. Water Maint. Man—1 at	\$
	Hrs. Water Maint. Man—2 at	\$
	Hrs. Garage Foreman at	\$
	Hrs. Labor— at	\$
	Hrs. Compressor at	\$
		\$
	Trucking	\$
	Pav't Patch	\$
		\$
		\$
		\$
		\$

St. 21

Ave. No. 21

ELIZABETH

Name of Owner _____

Labor and Mat'l. Report AUG. 6 1934

30'-4" 18'-0"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

OLD SHUT OFF AT MAIN

LSM-SC-6-1-67