

LABOR AND MATERIALS

1	Copper	} Connection	$\frac{3}{4}$	\$		
	Lead					
1	Curb	} Cock Valve T.S. & V.	$\frac{3}{4}$ in.	\$		
1	Service box			{ Short $3\frac{1}{2}$ x $4\frac{1}{2}$ Long $4\frac{1}{2}$ x $5\frac{1}{2}$ }	\$	
	Old returned					
28	Ft. $\frac{3}{4}$ in.	{ Copper C.S. C.P.	} Pipe at	\$		
	Nipples	in. at		\$		
	Bushings	to	in. at	\$		
1	Red'g Ins'g	Coupl'gs	to	in. at	\$	
	Union	in. at		\$		
	Meter	in. at		\$		
	Compound Joints	at		\$		
	Maintenance Foreman			\$		
	Hrs. Water Maint. Man—1	at		\$		
	Hrs. Water Maint. Man—2	at		\$		
	Hrs. Garage Foreman	at		\$		
	Hrs. Labor—	at		\$		
	Hrs. Compressor	at		\$		
	Trucking			\$		
	Pav't Patch			\$		
				\$		
				\$		
				\$		
				\$		
				\$		

St.
21.
Ave. No. 9

ELIZABETH

Name of Owner

Labor and Mat'l. Report OCT. 26 1927

● Curb Box

6" Main Elev. of
Main at tap 5'

Gate at ● ● Gate at

● Curb Box

NEW TAP NEW HOUSE