

Labor and Materials

1. Copper } Connection.....	\$ 3.20
Lead }	
1. Curb { Cock Valve }	\$ 1.00
{ T.S. & V. }	
1. Service Box { Short 3" x 4" }	\$ 1.40
Old returned { Long 4" x 5" }	
{ Buff. or Rdway }	
7. Ft. 3/4 in. { Copper } Pipe at.....	\$ 1.64
{ Galv. Iron }	
{ Cast Iron }	
..... Nipples..... in. at.....	\$
..... Bushings..... to..... in. at.....	\$
..... Red'g } Couplings..... to..... in. at.....	\$
..... Inc'g }	
..... Union..... in. at.....	\$
..... Meter..... in. at.....	\$
..... Lbs. Br. Stone at.....	\$
..... Lbs. Sand at.....	\$
..... Bags Cement at.....	\$
..... Paving Brick { Mack } at.....	\$
{ Red }	
{ Asphalt }	
..... Lead Joints at.....	\$
..... Leadite Joints at.....	\$
2. Hrs. Foreman at.....	\$ 1.25
2. Hrs. Common Labor at.....	\$ 1.00
1.2 Hrs. Common Labor at.....	\$ 4.88
..... Hrs. Mason at.....	\$
..... Hrs. Mason's Helper at.....	\$
..... Hrs. Compressor at.....	\$
..... Compensation Ins.....	\$ 1.9
..... Trucking.....	\$ 10.0
..... Builders' Use of Water.....	\$ 14.37
Total \$ 15.53	

Labor and Material Report

April 27 19 28

for 43 Elm St.



Curb Box

Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

Old Tap to Be dug up