

LABOR AND MATERIALS

1	Copper Lead	} Connection	$\frac{3}{4}$	_____	\$ _____
1	Curb				
1	Service box Old returned	{ Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ }	_____	_____	\$ _____
7	Ft. $\frac{3}{4}$ in.				
	Nipples _____ in.	at _____			\$ _____
	Bushings _____ to _____ in.	at _____			\$ _____
	Red'g } Inc'g }	Coupl'gs _____ to _____ in.	at _____		\$ _____
	Union _____ in.	at _____			\$ _____
	Meter _____ in.	at _____			\$ _____
	Compound Joints _____				\$ _____
	Maintenance Foreman _____				\$ _____
	Hrs. Water Maint. Man—1 _____	at _____			\$ _____
	Hrs. Water Maint. Man—2 _____	at _____			\$ _____
	Hrs. Garage Foreman _____	at _____			\$ _____
	Hrs. Labor— _____	at _____			\$ _____
	Hrs. Compressor _____	at _____			\$ _____
	Trucking _____				\$ _____
	Pav't Patch _____				\$ _____
					\$ _____
					\$ _____
					\$ _____
					\$ _____
					\$ _____

St. ELM No. 63
 Name of Owner _____
 TAX ID 3

Labor and Mat'l. Report OCT. 24 19 31



32-7 21-1

● Curb Box

6" Main Elev. of Main at tap 52'
 Gate at ● Gate at ●

● Curb Box

OLD TAP SHUT OFF