

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$ 1.31
1	Curb	Cock Valve T. S. & V.	$\frac{3}{4}$ in.	\$ 1.75
1	Service Box	Old returned {	Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$ 1.60
			Long $4\frac{1}{2} \times 5\frac{1}{2}$	
10	Ft.		Buff. or Rdway	
	$\frac{3}{4}$	in.	{	
			Copper	
			Galv. Iron.	
			Cast Iron	
			Pipe at 18	\$ 1.80
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Couplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
2 1/2	Hrs. Chauffeur	at .62 1/2		\$ 1.56
1	Hrs. Tapper	at .63		\$.63
9	Hrs. Labor	at .45		\$ 4.05
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$.19
	Trucking			\$ 1.-
	Builders Use of Water	no patch		\$ -
		Top 14 Miles by hand		\$
				\$
				\$
				\$
				\$
				\$
				\$ 13.89

8 8 - - 1940

St.

Pl.

Ave. No. 67

Name of Owner

Cowan

Labor and Mat'l. Report

1940

House to Be Razed



● Curb Box

6 Main

Elev. of Main at tap 6

Gate at ●

● Gate at

● Curb Box

Shut off at Curb

6-10-1974

Parson