

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$	\$	
1	Curb	Cock Valve T.S. & V.	$\frac{3}{4}$ in.	\$	
1	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$	
	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$	
11	Ft.	$\frac{3}{4}$ in. { Copper		\$	
		{ G.P.		\$	
		{ G.P.		\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g	Coupl'gs to in. at		\$	
	Inc'g			\$	
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man-1	at		\$	
	Hrs. Water Maint. Man-2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor	at		\$	
	Hrs. Compressor	at		\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	
				\$	

EMPIRE Ave. No. 12

Name of Owner
DAVISON

Labor and Mat'l. Report SEPT. 15 1937



27' 1" 30' 9"

● Curb Box

6" Main Elev. of Main at tap 4'

Gate at ● Gate at

● Curb Box

OLD TAP SHUT OFF