

L M-5C-2-1-54

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 32

Name of Owner  
John Dever

Labor and Mat'l. Report Aug. 26 1955

Gate at ● Gate at ●

Elev. of Main at tap 5'  
 Main 8" C.I.

Transite  
 West Curb Box Side

Eve-itts Ave  
 30' 8" 8"

East Side  
 Hydt. Hddt.

Labor and Mat'l. Report Aug. 26 1955

Name of Owner  
John Dever

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 32

L M-5C-2-1-54

L M-5C-2-1-54

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 32

Name of Owner  
John Dever

Labor and Mat'l. Report Aug. 26 1955

Gate at ● Gate at ●

Elev. of Main at tap 5'  
 Main 8" C.I.

Transite  
 West Curb Box Side

Eve-itts Ave  
 30' 8" 8"

East Side  
 Hydt. Hddt.

Labor and Mat'l. Report Aug. 26 1955

Name of Owner  
John Dever

St. \_\_\_\_\_  
 Pl. \_\_\_\_\_  
 Ave. No. 32

L M-5C-2-1-54

## LABOR AND MATERIALS

1	Copper	}	Connection	3/4"		\$ 2.71
	Lead					
1	Curb	}	Cock	3/4 in.		\$ 3.83
			Valve			
			T.S. & V.			
1	Service box	}	Short 3 1/2 x 4 1/2			\$ 4.69
	Old returned		Long 4 1/2 x 5 1/2			
			Buff. or Rdway			
9			Copper	}	Pipe at 45	\$ 10.35
23	Ft. 3/4 in.		G. I.			
			G. I.			
32	Nipples		in. at			\$
	Bushings		to in. at			\$
	Red'g	}	Coupl'gs	to	in. at	\$
	Inc'g					
	Union		in. at			\$
	Meter		in. at			\$
	Lead Joints		at			\$
	Compound Joints		at			\$
	Maintenance Foreman					\$
	Hrs. Water Maint. Man-1		at			\$
12	Hrs. Water Maint. Man-2		at 124			\$ 14.88
1	Hrs. Garage Foreman		at			\$ 1.59
10	Hrs. Labor		at 113			\$ 11.36
	Hrs. Compressor at					\$
	Compensation Ins. at \$ 4.29 per C					\$ 1.19
	Trucking					\$ 1.50
	Pav't Patch					\$ 9.00
	Tap by Gissard					\$
	8-26-55					\$
	O'head					\$
						\$ 61.04

52.04