

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$	\$
	Lead		
1	Curb	} Cock Valve } $\frac{3}{4}$ in.	\$
			T. S. & V.
1	Service box	} Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$
	Old returned		Long $4\frac{1}{4} \times 5\frac{1}{2}$
25	Ft. $\frac{3}{4}$ in.	} Copper } Pipe at	\$
			C.I.
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g } Inc'g }	} Coupl'gs to in. at	\$
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man—1	at	\$
	Hrs. Water Maint. Man—2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor—	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

EVERTS

St
Ave. No. 18

Name of Owner

Labor and Mat'l. Report

9-14 1935



58' 51''

● Curb Box

6" Main (C.I. 1970) Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

NEW TAP