

Labor and Materials

Copper	}	Connection	\$	
Lead			\$	
Curb	}	Cock Valve in	\$	
		T. S. & V.	\$	
Service Box	}	Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$	
Old returned		Long $4\frac{1}{2} \times 5\frac{1}{2}$			
		Buff. or Rdway			
Ft. in.	}	Copper	Pipe at	\$	
Nipples		Galv Iron			
		Cast Iron			
Bushings to in. at	\$		
Red'g	}	Conplings to in. at	\$
Inc'g			\$	
Union in. at	\$			
Meter in. at	\$			
Lead Joints	at	\$			
Leadite Joints	at	\$			
Hrs. Foreman	at	\$			
Hrs. Chauffeur	at	\$			
Hrs. Tapper	at	\$			
Hrs. Labor	at	\$			
Hrs. Labor	at	\$			
Hrs. Compressor	at	\$			
Compensation Ins.	\$			
Trucking	\$			
Builders Use of Water	\$			
		\$			
		\$			
		\$			
		\$			
		\$			
		\$			

St. 16?
 PR. Ave. No. 16?

Frederick

Name of Owner

Labor and Mat'l. Report April 13-38 19

● Curb Box

Main	Elev. of
	Main at tap
Gate at ●	● Gate at

● Curb Box