

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4"	\$
1	Curb Valve			} 3/4" in.
1	Service box Old returned	} { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 }		
6	Ft. 3/4" in.	} Copper Gal. Iron.	} Pipe at	\$
	Nipples			in. at
	Bushings	to	in. at	\$
	Red'g Inc'g	} Coupl'gs	to	in. at
	Union			
	Meter	in. at	\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

FIFTH St. No. 13  
 Name of Owner

Labor and Mat'l. Report JULY 27 1931



36'3" 36'11"

● Curb Box

6" Main Elev. of Main at tap 4'  
 Gate at ● Gate at

● Curb Box

NEW HOUSE