

LABOR AND MATERIALS

1	Copper	} Connection	3/4	_____	\$ _____
	Lead				
1	Curb	} Cock Valve	} 3/4 in.	_____	\$ _____
1	Service box	} Short 3 1/2 x 4 1/2	} _____	_____	\$ _____
	Old returned				
28	Ft.	} Copper	} _____	} Pipe at _____	\$ _____
	3/4 in.				
	Nipples	in. at _____	\$ _____		
1	Bushings	1/2 to 3/4 in. at _____	\$ _____		
	Red'g	} Coupl'gs _____ to _____ in. at _____	\$ _____		
	Inc'g				
	Union	in. at _____	\$ _____		
	Meter	in. at _____	\$ _____		
	Compound Joints	at _____	\$ _____		
	Maintenance Foreman	_____	\$ _____		
	Hrs. Water Maint. Man	—1 at _____	\$ _____		
	Hrs. Water Maint. Man	—2 at _____	\$ _____		
	Hrs. Garage Foreman	at _____	\$ _____		
	Hrs. Labor	at _____	\$ _____		
	Hrs. Compressor	at _____	\$ _____		
	Trucking	_____	\$ _____		
	Pav't Patch	_____	\$ _____		
		_____	\$ _____		
		_____	\$ _____		
		_____	\$ _____		
		_____	\$ _____		

FIFTH

St. No. 16

Name of Owner _____

Labor and Mat'l. Report

AUG 22 1930



31-1 23-9

● Curb Box

4" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box

OLD TAP DISCONNECTED