

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$ "	\$
1	Curb		} Cock Valve T. S. & V. } $\frac{3}{4}$ in.
1	Service box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$	
26	Ft. $\frac{3}{4}$ in.		} Copper } Pipe at
	Nipples	in. at	
	Bushings	to in. at	\$
	Red'g Inc'g	} Coupl'gs. to in. at	\$
	Union		in. at
	Meter	in. at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

St. FIFTH No. 20

Name of Owner _____

Labor and Mat'l. Report SEPT. 21 1926



30-3 23-10

● Curb Box

4" Main Elev. of Main at tap 4 1/2'

Gate at ● Gate at

● Curb Box