

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$	
	Lead				
1	Curb	} Cock Valve	3/4 in.	\$	
1	Service box	} Short 3 1/2 x 4 1/2		\$	
	Old returned				
28	Ft.	} Copper	3/4 in.	\$	
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
1	Red'g	} Coupl'gs	3/4	to in. at	\$
	ing				
	Union	in. at		\$	
	Meter	in. at		\$	
				\$	
	Compound Joints	at		\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man—1	at		\$	
	Hrs. Water Maint. Man—2	at		\$	
	Hrs. Garage Foreman	at		\$	
	Hrs. Labor—	at		\$	
	Hrs. Compressor	at		\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	
				\$	

FIFTH

St. No. 2

Name of Owner

Labor and Mat'l. Report JUNE 19 1925



29-7 22-11

● Curb Box

4" Main

Elev. of Main at tap 4'

Gate at ● Gate at

● Curb Box