LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection	3/4"	$ 1.31
1	Curb Cock ~~Valve~~ ~~T. S. & V.~~	3/4 in.	$ 1.75
1	Service Box ~~Old returned~~ Short 3½x4½ ~~Long 4½x5½~~ ~~Buff. or Rdway~~		$ 1.60
28	Ft. 3/4 in. Copper ~~Galv Iron~~ ~~Cast Iron~~ Pipe at		$ 5.04
	Nipples in. at		$
	Bushings to in. at		$
	Red'g Inc'g Couplings to in. at		$
	Union in. at		$
	Meter in. at		$
	Lead Joints at		$
	Leadite Joints at		$
	Hrs. Foreman at		$
2¼	Hrs. Chauffeur at	62½	$ 1.41
4¾	Hrs. Tapper at	-	$ 2.97
19	Hrs. Labor at	45	$ 8.55
	Hrs. Labor at		$
	Hrs. Compressor at		$
	Compensation Ins.		$ .40
	Trucking		$ 1.—
	Builders Use of Water	no patch	$ —
			$
			$
			$
	Tap by Hessel		$
			$ 24.03

1 2 5 - 1940

St. ~~Pl.~~ Ave. No. 24

Fifth

Name of Owner

Merritt

Labor and Mat'l. Report SEP 26 1940 19

Curb Box

4" Main

Elev. of Main at tap 5'

Gate at

Gate at

Curb Box

Old tap shut off