

LABOR AND MATERIALS

1	Copper	Connection	$\frac{3}{4}$	\$
1	Curb	Cock	$\frac{3}{4}$ in.	\$
1	Service box	Short $3\frac{1}{2} \times 4\frac{1}{2}$		\$
	Old returned	Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$
26	Ft. $\frac{3}{4}$ in.	Copper	Pipe at	\$
		Nipples	in. at	\$
		Bushings	to in. at	\$
		Red'g		\$
		Inc'g	Coupl'gs. to in. at	\$
		Union	in. at	\$
		Meter	in. at	\$
		Compound Joints	at	\$
		Maintenance Foreman		\$
		Hrs. Water Maint. Man	—1 at	\$
		Hrs. Water Maint. Man	—2 at	\$
		Hrs. Garage Foreman	at	\$
		Hrs. Labor	at	\$
		Hrs. Compressor	at	\$
		Trucking		\$
		Pav't Patch		\$
				\$
				\$
				\$
				\$
				\$

FIFTH

St. No. 28

Name of Owner

Labor and Mat'l. Report MAY 5 1927



● Curb Box

4" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE