LABOR AND MATERIALS

1	Copper ~~Lead~~ Connection	3/4"	$ 1.31
1	Curb { Cock ~~Valve~~ ~~T. S. & V.~~ }	3/4 in.	$ 1.75
1	Service Box ~~Old returned~~ { Short 3½x4½ ~~Long 4½x5½~~ ~~Buff. or Rdway~~ }		$ 1.60
8	Ft. 3/4 in. { Copper ~~Galv. Iron~~ ~~Cast Iron~~ } Pipe at	18	$ 1.44
	Nipples ____ in. at		$
	Bushings ____ to ____ in. at		$
	Red'g / Inc'g Couplings ____ to ____ in. at		$
	Union ____ in. at		$
	Meter ____ in. at		$
	Lead Joints at		$
	Leadite Joints at		$
	Hrs. Foreman at		$
1 1/2	Hrs. Chauffeur at	6 2½	$ 3.37½
1 1/2	Hrs. Tapper at	"	$ .94
5	Hrs. Labor at	45	$ 2.25
	Hrs. Labor at		$
	Hrs. Compressor at		$
	Compensation Ins.		$ .11
	Trucking		$ 1.—
	Builders Use of Water		$
			$
			$
	Tap by Heald		$
			$10.77½

SEP 29 - 1940

St. ~~Pl.~~ Fifth Ave. No. 31

Name of Owner

Kingsley

Labor and Mat'l. Report SEP 24 1940 19

4" Main

Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

All tap shut off 11