

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$
1	Curb			
		} Cock Valve T. S. & V.	3/4 in.	\$
1	Service box			
	Old notched	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2		\$
27	Ft. 3/4 in.			
		} Copper	} Pipe at	\$
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g	} Coupl'gs	to in. at	\$
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

FIFTH

St. No. 32

Name of Owner

Labor and Mat'l. Report JUNE 17 1927



● Curb Box

4" Main

Elev. of Main at tap 5 1/2'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE