

LABOR AND MATERIALS

1	Copper Lead	} Connection $\frac{3}{4}$	\$
1	Curb		\$
		} Cock Valve T.S. & V. } $\frac{3}{4}$ in.	\$
1	Service box Old returned		} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$
9	Ft. $\frac{3}{4}$ in.	} Copper Gal. Gal.	
	Nipples		in. at
	Bushings	to in. at	\$
	Red'g Inc'g	} Coupl'gs to in. at	\$
	Union		in. at
	Meter	in. at	\$
			\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man-1	at	\$
	Hrs. Water Maint. Man-2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

St. FIFTH
Ave. No. 56
Name of Owner _____

Labor and Mat'l. Report AUG. 20 1929



$34'-7''$ $31'-7''$

● Curb Box

6'' Main Elev. of Main at tap 5'

Gate at ● ● Gate at

● Curb Box

NEW HOUSE