

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$	
1	Lead } Cock		\$	
1	Curb } Valve	3/4 in.	\$	
1	Service box	{ Short 3-1/2 x 4-1/2	\$	
	Old returned	{ Long 4-1/2 x 5-1/2		
9'	Ft. 3/4 in. { Copper		\$	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g			
	Inc'g			
	Union	in. at	\$	
	Meter	in. at	\$	
			\$	
	Compound Joints at		\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man - 1 at		\$	
	Hrs. Water Maint. Man - 2 at		\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor at		\$	
			\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	
			\$	

FIFTH

St. ~~62~~ No. 62

Name of Owner
NOBERT

Labor and Mat'l. Report APR. 15, 1947

