

# LABOR AND MATERIALS

1	Copper } Connection		\$
1	Curb } Cock Valve	_____ in.	\$
1	Service box { Short 3-1/2 x 4-1/2		\$
	{ Long 4-1/2 x 5-1/2		\$
24'	Ft. 3/4" in. { Copper		\$
	{ Galv. Steel		\$
	Nipples _____ in. at _____		\$
	Bushings _____ to _____ in. at _____		\$
	Red'g _____		\$
	Inc'g _____		\$
	Union _____ in. at _____		\$
	Meter _____ in. at _____		\$
	Compound Joints at _____		\$
	Maintenance Foreman _____		\$
	Hrs. Water Maint. Man - 1 at _____		\$
	Hrs. Water Maint. Man - 2 at _____		\$
	Hrs. Garage Foreman _____ at _____		\$
	Hrs. Labor _____ at _____		\$
	Hrs. Compressor at _____		\$
	Trucking _____		\$
	Pav't Patch _____		\$
			\$
			\$
			\$
			\$
			\$
			\$

FIFTH

St. Ave. No. 71

Name of Owner

THOMAS

Labor and Mat'l. Report AUG. 7, 1931



29'5" 21'7"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

TAX ID # 309.11-12-25

● Curb Box