

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$
	Lead			
1	Curb	} Cock Valve	3/4 in.	\$
1	Service box	{	Short 3 1/2 x 4 1/2	\$
	Old returned			
26	Ft.	} Copper	3/4 in.	\$
	Nipples	in. at	\$	
1	Bushings	3/4 to 1/2 in. at	\$	
1	Ring	} Coupl'gs	3/4 to copper in. at	\$
	Lead			
	Union	in. at	\$	
	Meter	in. at	\$	
	Compound Joints	at	\$	
	Maintenance Foreman		\$	
	Hrs. Water Maint. Man-1	at	\$	
	Hrs. Water Maint. Man-2	at	\$	
	Hrs. Garage Foreman	at	\$	
	Hrs. Labor	at	\$	
	Hrs. Compressor	at	\$	
	Trucking		\$	
	Pav't Patch		\$	
			\$	
			\$	
			\$	
			\$	

FIFTH

St.

Ass. No. 8

Name of Owner

TAX ID # 309.12-15-7

Labor and Mat'l. Report

MAY 27 1925



● Curb Box

4" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD SHUT OFF