

LABOR AND MATERIALS

1	Copper	} Connection $\frac{3}{4}$		\$
	Lead			
1	Curb	} Cock Valve T.S. & V.	in.	\$
1	Service box Old returned	} Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$		\$
7	Ft. $\frac{3}{4}$ in.	} Copper Pipe	at	\$
	Nipples	in.	at	\$
	Bushings	to	in. at	\$
	Red'g Inc'g	} Coupl'gs	to	in. at
	Union	in.	at	\$
	Meter	in.	at	\$
				\$
	Compound Joints		at	\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1		at	\$
	Hrs. Water Maint. Man-2		at	\$
	Hrs. Garage Foreman		at	\$
	Hrs. Labor		at	\$
	Hrs. Compressor		at	\$
				\$
	Trucking			\$
	Pav't Patch			\$
				\$
				\$
				\$
				\$
				\$

FIFTH

St. No. 9

Name of Owner

TAX ID # 309.12-14-22

Labor and Mat'l. Report

MAY 15 1926



35'10" 38'9"

● Curb Box

4" Main

Elev. of Main at tap 5"

Gate at ●

● Gate at

● Curb Box

NEW TAP - NEW HOUSE