LABOR AND MATERIALS

1 ~~Copper~~ Lead } Connection 3/4 $ _____

1 Curb { Cock / ~~Valve~~ / ~~T.C. & V.~~ } 3/4 in. _____ $ _____

1 Service box { Short 3-1/2 x 4-1/2 / ~~Long 4-1/2 x 5-1/2~~ } Old returned _____ $ _____

10 Ft. 3/4 in. { ~~Copper~~ / G.I. / ~~Cut~~ } Pipe at _____ $ _____

_____ Nipples _____ in. at _____ $ _____

_____ Bushings _____ to _____ in. at _____ $ _____

_____ Red'g

_____ Inc'g

_____ Union _____ in. at _____ $ _____

_____ Meter _____ in. at _____ $ _____

_____ _____ $ _____

_____ Compound Joints at _____ $ _____

_____ Maintenance Foreman _____ $ _____

_____ Hrs. Water Maint. Man - 1 at _____ $ _____

_____ Hrs. Water Maint. Man - 2 at _____ $ _____

_____ Hrs. Garage Foreman _____ at _____ $ _____

_____ Hrs. Labor _____ at _____ $ _____

_____ Hrs. Compressor at _____ $ _____

_____ _____ $ _____

_____ Trucking _____ $ _____

_____ Pav't Patch _____ $ _____

_____ _____ $ _____

_____ _____ $ _____

_____ _____ $ _____

_____ _____ $ _____

$ _____

FIRST St. ~~Ave.~~ No. 14

Name of Owner
TAX ID # 309.12-8-6

Labor and Mat'l. Report ~~for~~ JUNE 11 & 12, 1925

23'10" 31'

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box