

LABOR AND MATERIALS

1 Copper } Connection $\frac{3}{4}$	\$ 1.80
Lead }	
1 Curb } Cock Valve } $\frac{3}{4}$ in.	\$ 1.96
T.S. & V. }	
1 Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$ }	\$ 1.87
Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$ }	
Buffer Rdway }	
21 Ft. $\frac{3}{4}$ in. } Copper } Pipe at 19	\$ 4.56
Galv Iron }	
Cast Iron }	
Nipples..... in. at	\$
Bushings..... to..... in. at	\$
Red'g } Couplings..... to..... in. at	\$
Inc'g }	
Union..... in. at	\$
Meter..... in. at	\$
Lead Joints at	\$
Leadite Joints at	\$
Hrs. Foreman at	\$
14 Hrs. Chauffeur at $68\frac{3}{4}$	\$ 9.63
Hrs. Tapper at	\$
1.0 Hrs. Labor at 6.0	\$ 6.00
Hrs. Labor at	\$
Hrs. Compressor at	\$
Compensation Ins. 2.669	\$ 4.2
Trucking	\$ 1.00
Builders Use of Water	\$ 9.36
Tap by Marsinske'	\$
.....	\$
.....	\$
.....	\$
\$ 36.55	

37-44

St.
 Pl.
 Ave. No. 17

Name of Owner
Smegars

Labor and Mat'l. Report Nov 14 1944

6 Main
Elev. of Main at tap 5

Gate at ●
● Gate at

TAX ID # 309.12-1-15

● Curb Box