

# LABOR AND MATERIALS

Copper } Connection _____	\$ _____
Lead } _____	\$ _____
1 Curb } Cock } 3/4 in. _____	\$ _____
	Valve } _____
	S.S. & V. } _____
1 Service box { Short 3-1/2 x 4-1/2 } _____	\$ _____
Old returned { Long 4-1/2 x 5-1/2 } _____	\$ _____
10.8 Ft. in. { Copper } Pipe at _____	\$ _____
	_____
_____ Nipples _____ in. at _____	\$ _____
_____ Bushings _____ to _____ in. at _____	\$ _____
_____ Red'g _____	\$ _____
_____ Inc'g _____	\$ _____
_____ Union _____ in. at _____	\$ _____
_____ Meter _____ in. at _____	\$ _____
_____ _____	\$ _____
_____ Compound Joints at _____	\$ _____
_____ Maintenance Foreman _____	\$ _____
_____ Hrs. Water Maint. Man - 1 at _____	\$ _____
_____ Hrs. Water Maint. Man - 2 at _____	\$ _____
_____ Hrs. Garage Foreman _____ at _____	\$ _____
_____ Hrs. Labor _____ at _____	\$ _____
_____ Hrs. Compressor at _____	\$ _____
_____ _____	\$ _____
_____ Trucking _____	\$ _____
_____ Pav't Patch _____	\$ _____
_____ _____	\$ _____
_____ _____	\$ _____
_____ _____	\$ _____
_____ _____	\$ _____
_____ _____	\$ _____

St. FIRST No. 22  
 Name of Owner \_\_\_\_\_

Labor and Mat'l. Report OCT. 6, 1923



23'6" 30'4"

● Curb Box

\_\_\_\_\_ Main Elev. of Main at tap \_\_\_\_\_

Gate at ● Gate at ●

● Curb Box