

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Curb	Cock Valve	3/4" in.	\$
1	Service box	Short 3 1/2 x 4 1/2		
	Old returned	Long 4 1/2 x 5 1/2		
		Buff or Rdway		\$
25	3/4 in.	Copper G.I. Pipe at		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by G. I. Ford			\$
	5-12-60			\$
	O'head			\$

✓

St. First
 Pl. 23
 Ave. No. 23

Name of Owner Bertha Graves

Labor and Mat'l. Report May 12 1960

6" Main
 23' 9"
 29' 9"
 Curb Box
 closed-in
 closed-in
 Elev. of Main at tap
 Gate at
 Gate at
 Tap at Main
 Curb Box

TAX ID # 309.12-1-12

LSM-5C-2-5 56