

Labor and Materials

1	Copper	{	Connection	5		\$
	Lead	}				
1	Curb	{	Cock		in	\$
		}	Valve			
			T. S. & V.			
1	Service Box	{	Short	3 1/2 x 4 1/2		\$
	Old returned	}	Long	4 1/2 x 5 1/2		
			Buff. or Rdway			
24	Ft.		Copper		Pipe at	\$
3/4	in.		Galv Iron			
			Cast-Iron			
	Nipples				in. at	\$
	Bushings				to in. at	\$
	Red'g	{	Conplings		to in. at	\$
	Inc'g	}				
	Union				in. at	\$
	Meter				in. at	\$
	Lead Joints				at	\$
	Leadite Joints				at	\$
	Hrs. Foreman				at	\$
	Hrs. Chauffeur				at	\$
	Hrs. Tapper				at	\$
	Hrs. Labor				at	\$
	Hrs. Labor				at	\$
	Hrs. Compressor				at	\$
	Compensation Ins.					\$
	Trucking					\$
	Builders Use of Water					\$
						\$
						\$
						\$
						\$
						\$
						\$
						\$
						\$

First

Name of Owner
Lapham & Griffing

Labor and Mat'l. Report 4/15 1918

St. Pt. Ave. No. 3 1/2

#3

440" 31/2"

Curb Box

6" Main

Gate at ●

Elev. of Main at tap

● Gate at

● Curb Box