

LABOR AND MATERIALS

1	Copper	} Connection	3/4	\$
1	Curb			} 3/4 in.
1	Service box	{	Short 3-1/2 x 4-1/2	
	Old returned			{
23	Ft. 3/4 in.	} Copper	Pipe at	
	Nipples			} in. at
	Bushings	} to in. at	\$	
	Red'g			\$
	Inc'g		\$	
	Union	} in. at	\$	
	Meter		} in. at	\$
	Compound Joints at	\$		
	Maintenance Foreman	\$		
	Hrs. Water Maint. Man - 1 at	\$		
	Hrs. Water Maint. Man - 2 at	\$		
	Hrs. Garage Foreman at	\$		
	Hrs. Labor at	\$		
	Hrs. Compressor at	\$		
	Trucking	\$		
	Pav't Patch	\$		
		\$		
		\$		
		\$		
		\$		
		\$		

FIRST

St. No. 35

Name of Owner
TAX ID # 309.12-1-6

Labor and Mat'l. Report ~~1931~~ MAR. 30, 1931



21'-8" 34'-10"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

OLD TAP DISCONNECTED