

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$
1	Curb } Cock Valve	3/4 in.	\$
1	Service box } Short 3-1/2 x 4-1/2		\$
	Old returned } Long 4-1/2 x 5-1/2		\$
25	Ft. 3/4 in. } Copper Pipe at		\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman at		\$
	Hrs. Labor at		\$
	Hrs. Compressor at		\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

St. FIRST Ass. No. 112

Name of Owner _____
TAX ID # 309.12-1-18

Labor and Mat'l. Report 19 JULY 13, 1928



35' 4" 18' 6"

● Curb Box

4" Main Elev. of Main at tap 52'

Gate at ● SPRING ST ● Gate at

● Curb Box

TAP ON SPRING ST.
OLD TAP TO BE DUG UP