

LABOR AND MATERIALS

1	Copper } Connection <u>3/4</u>	\$ _____
	lead } Cock	
1	Curb } Valve } <u>3/4</u> in.	\$ _____
	T.S. & V. }	
1	Service box { Short 3-1/2 x 4-1/2 } Old returned { Long 4-1/2 x 5-1/2 }	\$ _____
26	Ft. <u>3/4</u> in. { Copper } { Gal. }	Pipe at \$ _____
	Nipples _____ in. at _____	\$ _____
	Bushings _____ to _____ in. at _____	\$ _____
	Red'g _____	
	Inc'g _____	
	Union _____ in. at _____	\$ _____
	Meter _____ in. at _____	\$ _____
	_____	\$ _____
	Compound Joints at _____	\$ _____
	Maintenance Foreman _____	\$ _____
	Hrs. Water Maint. Man - 1 at _____	\$ _____
	Hrs. Water Maint. Man - 2 at _____	\$ _____
	Hrs. Garage Foreman _____ at _____	\$ _____
	Hrs. Labor _____ at _____	\$ _____
	Hrs. Compressor at _____	\$ _____
	_____	\$ _____
	Trucking _____	\$ _____
	Pav't Patch _____	\$ _____
	_____	\$ _____
	_____	\$ _____
	_____	\$ _____
	_____	\$ _____
	_____	\$ _____
	_____	\$ _____

RD

St.

Rt.

F.T. AMHERST

Ave. No. 22

Name of Owner

Labor and Mat'l. Report 1929, MAY 14



67'6" 56'6"

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

SAMUEL DRUYN HOUSE

NEW HOUSE