## **LABOR AND MATERIALS**

2	
Copper Connection	
TSHORY }	_
Service box Short 3-1/2 x 4-1/2 Sold returned Long 4 1/2 x 5-1/2	\$
26 Ft. $\frac{3}{4}$ in. $\binom{\text{Copper}}{\text{Coll}}$ Pipe at	_ \$
Nipples in. at	_ \$
Bushings to in. at	_ \$
Red'g	
Inc'g	
Union in. at	_ \$
Meter in. at	_ s
	_ \$
Compound Joints at	
Maintenance Foreman	_ \$
Hrs. Water Maint. Man - 1 at	_ \$
Hrs. Water Maint. Man - 2 at	_ \$
Hrs. Garage Foreman at	_ \$
Hrs. Labor at	\$
Hrs. Compressor at	_ \$
	_ \$
Trucking	_ \$
Pav't Patch	
	_ \$
\$\$	_ \$
-	_ \$
	s
	s

	RD. <del>St</del> .	
FT. AMHER	5 / Ava. No 2	
Name of Owner		
Labor and Mat'l. Report	1930, SEPT. 4	
58-	-5 65=3	
	Curb Box	
6Main	Elev. of Main at tap	55
Gate at ●		Gate at
	-	
<del></del>	Curb Box	
NEW HOUSE	olong N Nag	
ROBDIE H	LIGLEY	