

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Lead	Cock		\$
1	Curb	Valve	3/4 in.	\$
		T.S. & V.		\$
1	Service box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		\$
		Buff or Rdway		\$
12	Ft.	Copper	Pipe at	\$
	3/4 in.	G.I.		\$
		G.I.		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g			\$
	Inc'g	Coupl'gs to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints at			\$
	Compound Joints at			\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1 at			\$
	Hrs. Water Maint. Man-2 at			\$
	Hrs. Garage Foreman at			\$
	Hrs. Labor at			\$
	Hrs. Compressor at			\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pay't Patch			\$
	Tap by Wadleigh &			\$
	barreau 6-18-57			\$
				\$
	O'head			\$
				\$

V
St. Red. 39
Pl.
Ave. No. 11

Ft. Pemberton

Name of Owner
Mr. G. Gallaud

Labor and Mat'l. Report June 18 1957

6" Main Elev. of Main at tap 6'

Gate at ● ● Gate at

● Curb Box

LSM-5C-2-5 56