

LSM-5C-6-1-45

Garage

92'

141'

Curb Box

Measured in 10-20-67

Gate at ●

Main at tap ●

Elev. of Main 5 1/2

Curb Box

20' 6"

38' 3"

47' 6"

Tree

Elev. of Main at tap 5 1/2

Gate at ●

Gate at ●

Labor and Mat'l. Report Oct 24 1946

Name of Owner Mr. Mulligan

St. Amberst Ave. No. 13

98-46

LSM-5C-6-1-45

98-46

Fort Amberst

St. Amberst Ave. No. 13

Name of Owner Mr. Mulligan

Labor and Mat'l. Report Oct 24 1946

Curb Box

20' 6"

38' 3"

47' 6"

Tree

Elev. of Main at tap 5 1/2

Gate at ●

Gate at ●

Measured in 10-20-67

Curb Box

92'

141'

Garage

LSM-5C-6-1-45

LABOR AND MATERIALS

| | | | | | |
|---|--|--|--|--------------|----------|
| 1 | Copper Lead | } Connection | $\frac{3}{4}$ | | \$ 1.78 |
| 1 | Curb | { Clock Valve F.S. & V. | $\frac{3}{4}$ | in. | \$ 2.61 |
| 1 | Service box Old returned | { Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway | | | \$ 1.82 |
| 9 | Ft. | $\frac{3}{4}$ in. | { Copper Galv. Iron Cast Iron | } Pipe at 73 | \$ 2.07 |
| | Nipples | in. at | | | \$ |
| | Bushings | to in. at | | | \$ |
| | Red'g Inc'g | { Couplings | to | in. at | \$ |
| | Union | in. at | | | \$ |
| | Meter | in. at | | | \$ |
| | Lead Joints | at | | | \$ |
| | Compound Joints | at | | | \$ |
| 2 | Hrs. Foreman at | WWM | 92 1/2 | | \$ 1.85 |
| | Hrs. Chauffeur at | | | | \$ |
| | Hrs. Tapper at | | | | \$ |
| | Hrs. Labor at | | | | \$ |
| 7 | Hrs. Labor at | 71 1/2 | | | \$ 5.01 |
| | Hrs. Compressor at | | | | \$ |
| | Compensation Ins. | | | | \$ 19 |
| | Trucking | | | | \$ 1.00 |
| | Builders Use of Water | | | | \$ 5.00 |
| | Topp & Miller | | | | \$ |
| | Pipes furnished by | | | | \$ |
| | Owens | | | | \$ |
| | | | | | \$ 19.26 |

68.9

