

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{1}{2}$	\$	
1	Curb	Cock Valve P.S. & V.	$\frac{3}{4}$ in.	\$	
	Service box	Short 3-1/2 x 4-1/2		\$	
	Old returned	Long 4-1/2 x 5-1/2		\$	
8	Ft.	$\frac{3}{4}$ in. Copper G.I.	Pipe at	\$	
	Nipples		in. at	\$	
1	Bushings	$\frac{1}{2} \times \frac{3}{4}$ to	in. at	\$	
	Red'g			\$	
	Inc'g			\$	
	Union		in. at	\$	
	Meter		in. at	\$	
				\$	
	Compound Joints at			\$	
	Maintenance Foreman			\$	
	Hrs. Water Maint. Man - 1 at			\$	
	Hrs. Water Maint. Man - 2 at			\$	
	Hrs. Garage Foreman		at	\$	
	Hrs. Labor		at	\$	
	Hrs. Compressor at			\$	
				\$	
	Trucking			\$	
	Pav't Patch			\$	
				\$	
				\$	
				\$	
				\$	

St. FOURTH
 Ave. No. 3
 Name of Owner _____

Labor and Mat'l. Report JUNE 18, 1923



14'6" 29'
 ● Curb Box

6" Main Elev. of Main at tap 4'
 Gate at ● ● Gate at

● Curb Box