

LABOR AND MATERIALS

1	Copper } Connection	3/4	\$
1	Lead } Cock Valve	3/4 in.	\$
		T.S. & V.	
1	Service box	{ Short 3-1/2 x 4-1/2 } { Long 4-1/2 x 5-1/2 }	\$
26	Ft. 3/4 in. { Copper } Old returned	Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
			\$
	Compound Joints at		\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1 at		\$
	Hrs. Water Maint. Man - 2 at		\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor at		\$
			\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$

4th St. No. 16
 Name of Owner _____
 TAX ID # 309.12-14-12
 Labor and Mat'l. Report 1936, SEPT. 14

CELLAR WALL

26-6 35-11

● Curb Box

6" Main Elev. of Main at tap 5'
 Gate at ● Gate at

● Curb Box

NEW HOUSE