

LABOR AND MATERIALS

1	Copper	Connection	\$
1	Curb	Cock Valve T.S. & V. } in.	\$
1	Service box	{ Short 3-1/2 x 4-1/2 } { Long 4-1/2 x 6-1/2 }	\$
26	Ft.	3/4 in. { Copper } Pipe at	\$
	Nipples	in. at	\$
	Bushings	to in. at	\$
	Red'g		
	Inc'g		
	Union	in. at	\$
	Meter	in. at	\$
	Compound Joints	at	\$
	Maintenance Foreman		\$
	Hrs. Water Maint. Man - 1	at	\$
	Hrs. Water Maint. Man - 2	at	\$
	Hrs. Garage Foreman	at	\$
	Hrs. Labor	at	\$
	Hrs. Compressor	at	\$
	Trucking		\$
	Pav't Patch		\$
			\$
			\$
			\$
			\$
			\$
			\$

4th St. No. 18
 Name of Owner _____

Labor and Mat'l. Report 19 36, SEPT. 11

CELLAR WALL

26-5 32

● Curb Box

6" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

NEW HOUSE

LABOR AND MATERIALS

_____ Copper } Connection _____ \$ _____	
_____ Lead } _____	
_____ Curb } Cock } _____ in. _____ \$ _____	
_____ } Valve } _____	
_____ } T.S. & V. } _____	
_____ Service box { Short 3-1/2 x 4-1/2 } _____ \$ _____	
_____ Old returned { Long 4-1/2 x 5-1/2 } _____	
_____ Ft. _____ in. { Copper } Pipe at _____ \$ _____	
_____ } G.I. }	
_____ } C.I. }	
_____ Nipples _____ in. at _____ \$ _____	
_____ Bushings _____ to _____ in. at _____ \$ _____	
_____ Red'g _____	
_____ Inc'g _____	
_____ Union _____ in. at _____ \$ _____	
_____ Meter _____ in. at _____ \$ _____	
_____ _____ \$ _____	
_____ Compound Joints at _____ \$ _____	
_____ Maintenance Foreman _____ \$ _____	
_____ Hrs. Water Maint. Man - 1 at _____ \$ _____	
_____ Hrs. Water Maint. Man - 2 at _____ \$ _____	
_____ Hrs. Garage Foreman _____ at _____ \$ _____	
_____ Hrs. Labor _____ at _____ \$ _____	
_____ Hrs. Compressor at _____ \$ _____	
_____ _____ \$ _____	
_____ Trucking _____ \$ _____	
_____ Pav't Patch _____ \$ _____	
_____ _____ \$ _____	
_____ _____ \$ _____	
_____ _____ \$ _____	
_____ _____ \$ _____	
_____ _____ \$ _____	

Fovr TM St. _____
 Pl. _____
 Ave. No. 18
 Name of Owner _____
 Labor and Mat'l. Report 19 7-3-2013

