

LABOR AND MATERIALS

1	Copper lead	} Connection	$\frac{3}{4}$	\$	_____
1	Curb		} Cock Valve T.S. & V.	$\frac{3}{4}$ in.	\$
1	Service box Old returned	} Short 3-1/2 x 4-1/2 Long 2-1/2 x 5-1/2			\$
27	Ft.		} Copper Gal. Gal.	$\frac{3}{4}$ in.	Pipe at
	Nipples			_____ in.	at
	Bushings		_____ to _____	in. at	\$ _____
	Red'g				\$ _____
	Inc'g				\$ _____
	Union		_____ in.	at	\$ _____
	Meter		_____ in.	at	\$ _____
					\$ _____
	Compound Joints			at	\$ _____
	Maintenance Foreman				\$ _____
	Hrs. Water Maint. Man - 1			at	\$ _____
	Hrs. Water Maint. Man - 2			at	\$ _____
	Hrs. Garage Foreman			at	\$ _____
	Hrs. Labor			at	\$ _____
	Hrs. Compressor			at	\$ _____
					\$ _____
	Trucking				\$ _____
	Pav't Patch				\$ _____
					\$ _____
					\$ _____
					\$ _____
					\$ _____
					\$ _____

St. FOURTH Ave. No. 47

Name of Owner BALL

Labor and Mat'l. Report 19 37, OCT. 13



MEASUREMENT
FOR LOT 32 42-8
TAP

● Curb Box

6" Main IRON MAIN Elev. of Main at tap 5'

Gate at ● Gate at ●

● Curb Box

NEW HOUSE